









							
Ax12	Bx12	Cx12 ø6 x 30	Dx 4 ø4x30mm	Ex 4 ø3x12mm	Fx 2	Gx 1	Hx 2 ø4x20mm
							
Ix 2	Jx 4	Kx 12					



PASO 1










PASO 2




PASO 3



PASO 4



PASO 5



PASO 6

